

TURBO DEPARTMENT

- 1) Turbo charger items
 - Volvo FM12, FM10, FL10, FM400, FM440
 - Scania S124, S114, S113, K270, R420



2) Every item brought in for remanufacture (sometimes referred as item reconditioning) undergoes an initial inspection and is graded before being carefully dismantled for cleaning and degreasing. Journal bearings, seal rings and other small item are discarded as a matter of policy



- 3) The equipment that used to process
 - Wash Machine Bearing and turbine housings are cleaned in a high temperature pressure wash tank and ultrasonic cleaner to fully ensure removal of carbon deposits



Oven Machine – To remove all dirt and rust attached to the turbine at very high temperatures to 750 Celsius.




 Sand Blasting – All major components such as turbine shaft wheels, compressor wheels and housings are checked against the manufacturer specifications. Components that do not meet the required tolerance / high standard are replaced as matter of course



4) Checking part and installation item process





- 5) Equipment provided
 - Balancing Machine



• A Test result for Balancing Machine

	Balancing	Certificate	
Workshop:	Turbo Pe	formance S/B	
Address:	25 Jalan SBC 5, Taman Seri Batu Caves		
Town:	68100 Batu Caves, Selangor Darul Ehsan		
Country:	Malaysia	•	
Phone Number:			
Fax:			
E-mail:			
Internet:			
Machine Serial N*:	4019200-	001	
Rotor Type:	Complete Rotor		
Rotor Model:	S3A		
Rotor PartNumber:	0.2770.000		
Left Residual Unbal	lance:	Right Residual Unbalance:	
8.08 gmm		1.92 gmm	
Left Tolerance:		Right Tolerance:	
9.60 gmm		9.60 gmm	
Test result left	(A	Test result right	
Balanced		Balanced	
Residuai Static Unbalance:		6.25gmm	
Residual Couple Unbalance:		4.97gmm	
Customer:		QUIPMENT J/C 108169	
Certificate N*:	0		
Comments:			100
lime:	9:23 AM		
Date:	7/31/2015		10
Operator:	ADMIN -		

- 6) Test Bench for turbo complete assy
 - To know the result OK graft, will show PRESS IN and PRESSURE OUT for stability and not too much different. If not, turbo test failed





7) Test result for turbo for complete assy

