



TURBO PERFORMANCE SDN BHD
Solution for New & Remanufactured Turbocharges

OTHERS DEPARTMENT

1) Air compressor items

- Volvo FM12 V1, FM12 V2, FM400, FM10, FL10, FH12
- Scania S94, S113, S124 (Knorr & Wabco)



- 2) Every item brought in for remanufacture (sometimes referred as item reconditioning) undergoes an initial inspection and is graded before being carefully dismantled for cleaning and degreasing. Bearing, piston, piston ring and other small items are discarded as a matter of policy



3) The equipment that used to process



- Wash Machine – Head, Crankshaft, Piston and block air compressor are cleaned in a high temperature pressure wash tank and ultrasonic cleaner to fully ensure removal of carbon deposits



- Sand Blasting – All major components such as head, block and plat are checked against the manufacturer specifications. Components that do not meet the required tolerance / high standards are replaced as matter of course



4) Checking part and installation item process



BHD
charges


5) Equipment provided

- Air compressor Test Bench
 - i. Pressure bar will up until 8 (TEST OK)
 - ii. If below than 8 pressure, compressor will slow (NOT PASS)



- Test result

公司名称:



顾客名称: 维修编号: 0-04083 产品编号: .01 2. 2015-08-07 10:48

车 款: WABCO FL10 技术人员编号: 207 日期: 2015-08-07 时间: 10:48:04