


UNIT INJECTOR DEPARTMENT

- 1) Unit Injector item
 - Volvo FM12 V1, FM12 V2, FM400, FM440
 - Scania S124, S114, S113, K270, R420 (Bosch an Delphi



2) Every item brought in for remanufacture (sometimes referred as item reconditioning) undergoes an initial inspection and is graded before being carefully dismantled for cleaning and degreasing. Piston, seal rings and other small item are discarded as a matter of policy







3) Checking part and installation item process



4) Equipment provided

• Unit Injector Test Bench









Test Result

- i. Test Unit injector has 3 times if all pressure enough and stable
- ii. If pressure have problem and not stable, the result will failed

